

CENTURY *Equipment*

Please contact your service representative with questions or to arrange service for your Otterbine fountain today.

JOHN AUSTIN
(937) 623-6875

ROB DYE
(330) 329-4468

TOLEDO

5959 Angola Rd., Toledo, OH 43615

1-800-346-0066

Phone: (419) 865-7400 Fax: (419) 865-8215

CINCINNATI

8650 Berk Blvd., Hamilton, OH 45015

1-800-666-2460

Phone: (513) 285-1800 Fax: (513) 285-1805

COLUMBUS

4199 Leap Rd., Hilliard, OH 43026

1-800-321-4466

Phone: (614) 771-9995 Fax: (614) 771-9990

CLEVELAND

26565 Miles Rd., Ste. 100

Warrensville Heights, OH 44128

1-800-522-8676

Phone: (216) 292-6911 Fax: (216) 292-7635


CENTURY *Equipment*

PO BOX 352889
TOLEDO OH 43635-2889

RETURN SERVICE REQUESTED

CENTURY EQUIPMENT

Authorized Otterbine
Service Center



**ASK ABOUT
WARRANTY
UPDATES!**

OTTERBINE FOUNTAIN

2008 / 2009 Maintenance Programs

CENTURY EQUIPMENT

Authorized Otterbine Field Service Center

- 10 Years Sales and Service of Otterbine Equipment
- Two Certified Road Technicians
- Complete Otterbine Parts Inventory

Authorized Otterbine Service Center – Cleveland

- Otterbine - Test Panel with Amp. Meters
 - Bench test and run motors
- Slaughter - Hipot Tester
 - High voltage motor windings integrity test
 - Test motors for electrical short
- UEI - Meg. Tester
 - Electric motor insulation test
 - Test motors for electrical short
- Gast - Vacuum and Compressor
 - vacuum leak test
- Capacitor Tester
- 100 Gallon Water Tank
- Wash bay with hot water pressure wash.
- **FREE** heated storage available for service units.

All Otterbine units serviced in our shop are opened with low pressure compressor, less than 5 psi. Serviced units are also sealed and tested under vacuum, per manufacturer specifications. All units are tested under vacuum to ensure leak free performance.

CONCEPT 3 FOUNTAINS

Program A: (Recommended between year 3 and 4)

Maintenance includes: oil change, new oil plugs, check bearing wear, perform electrical readings on windings and clean unit.

Cost: \$295.00

Program B: (Recommended every 6 years)

Maintenance includes: new seals, O-rings, oil change, complete tear down of unit to inspect bearing wear, perform electrical readings on windings and a thorough cleaning of unit.

Cost: \$450.00



The above maintenance programs are designed to meet Otterbine / Barebo service recommendations. Above pricing does not include pick up or delivery of units. Call our office for arrangements or have the units dropped off at a Century Equipment near you. Any additional parts or service needed, resulting from bad bearings or motor failures will be an additional cost. An estimate for additional charges will be provided to customer for authorization before repairs are completed. Other Otterbine or golf irrigation on-site service is available. Century Equipment field service hourly rates apply.

CONCEPT 2 FOUNTAINS

Program A: (Recommended biannual)

Maintenance includes: oil change, new oil plugs, check bearing wear, perform electrical readings on windings and clean unit.

Cost: \$450.00

Program B: (Recommended every 6 years)

Maintenance includes: new seals, O-rings, oil change, complete tear down of unit to inspect bearing wear, perform electrical readings on windings and a thorough cleaning of unit.

Cost: \$575.00

* Parts are no longer available for service or repair of Concept 1 1-5 HP units.

