

# CENTURY *Equipment*

Please contact your service representative with questions or to arrange service for your Otterbine fountain today.

**JOHN AUSTIN**  
(937) 623-6875

**ROB DYE**  
(330) 329-4468



Shop Online

[www.centuryequip.com](http://www.centuryequip.com)

## **TOLEDO**

5959 Angola Rd., Toledo, OH 43615

**1-800-346-0066**

Phone: (419) 865-7400 Fax: (419) 865-8215

## **CINCINNATI**

8650 Berk Blvd., Hamilton, OH 45015

**1-800-666-2460**

Phone: (513) 285-1800 Fax: (513) 285-1805

## **COLUMBUS**

4199 Leap Rd., Hilliard, OH 43026

**1-800-321-4466**

Phone: (614) 771-9995 Fax: (614) 771-9990

## **CLEVELAND**

26565 Miles Rd., Ste. 100

Warrensville Heights, OH 44128

**1-800-522-8676**

Phone: (216) 292-6911 Fax: (216) 292-7635

Revised: December 2009

**CENTURY** *Equipment*

PO BOX 352889  
TOLEDO OH 43635-2889

RETURN SERVICE REQUESTED

CENTURY EQUIPMENT

Authorized Otterbine  
Service Center



TAKE ADVANTAGE  
OF OUR WINTER  
SERVICE RATES

# OTTERBINE FOUNTAIN

## Maintenance Program

### CENTURY EQUIPMENT

#### Authorized Otterbine Field Service Center

- 10 Years Sales and Service of Otterbine Equipment
- Two Certified Road Technicians
- Complete Otterbine Parts Inventory
- Otterbine - Test Panel with Amp. Meters
  - Bench test and run motors
- Slaughter - Hipot Tester
  - High voltage motor windings integrity test
  - Test motors for electrical short
- UEI - Meg. Tester
  - Electric motor insulation test
  - Test motors for electrical short
- Gast - Vacuum and Compressor
  - vacuum leak test
- Capacitor Tester
- 100 Gallon Water Tank
- Wash bay with hot water pressure wash.
- **FREE** heated storage available for service units.

All Otterbine units serviced in our shop are opened with low pressure compressor, less than 5 psi. Serviced units are also sealed and tested under vacuum to ensure leak free performance per manufacturer specifications.

### QUICK TIPS

When installing and removing units from the water never pull on the power cord.

Prior to installation and during inspection be sure the power cord strain relief is secure.

Always reapply Dielectric Compound to electrical connections after the connection has been taken apart.

Concept 3 and Concept 2 units should never be stored or transported in an upside down position. C3 units should only be transported in the upright position with the float removed or supported from below.

Otterbine has specific recommendations for Low Voltage Hi Intensity MR 16 Light kits. These recommendations need to be followed to maximize both fixture and bulb life.

When replacing MR 16 bulbs be sure to replace the o-ring to insure a water tight seal.

Factory Authorized Maintenance is required to uphold some warranties.

### Understanding Otterbine Serial Numbers:

XXXX -	XXXX -	XXXXX
HP &	Date Code	Internal Code
Electrical Rating		



LARGE AERATING FOUNTAINS



AERATING FOUNTAINS



INDUSTRIAL AERATORS

The above maintenance programs are designed to meet Otterbine / Barebo service recommendations. Above pricing does not include pick up or delivery of units. Call our office for arrangements or have the units dropped off at a Century Equipment near you. Any additional parts or service needed, resulting from bad bearings or motor failures will be an additional cost. An estimate for additional charges will be provided to customer for authorization before repairs are completed. Other Otterbine or golf irrigation on-site service is available. Century Equipment field service hourly rates apply.

### CONCEPT 3 FOUNTAINS

**Program A: (Recommended between year 3 and 4)**  
Maintenance includes: oil change, new oil plugs, check bearing wear, perform electrical readings on windings and clean unit.

**Cost: \$295.00**

#### **Program B: (Recommended every 6 years)**

Maintenance includes: new seals, O-rings, oil change, complete tear down of unit to inspect bearing wear, perform electrical readings on windings and a thorough cleaning of unit.

**Cost: \$450.00**

### CONCEPT 2 FOUNTAINS

#### **Program A: (Recommended biannual)**

Maintenance includes: oil change, new oil plugs, check bearing wear, perform electrical readings on windings and clean unit.

**Cost: \$450.00**

#### **Program B: (Recommended every 6 years)**

Maintenance includes: new seals, O-rings, oil change, complete tear down of unit to inspect bearing wear, perform electrical readings on windings and a thorough cleaning of unit.

**Cost: \$575.00**

\* Parts are no longer available for service or repair of Concept 1 1-5 HP units.